

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. 750

/SAC/2023

Date : 3/11/23

BUILDING SAFETY CERTIFICATE.

Certified that the existing building "Holy Cross School"(name of the building or premises) at **Khandwa Road, Near Khandwa Naka, Indore (MP)** (address) comprised of one basement (s) and Two upper floors owned / occupied by **Holy Cross School** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Work Department District Sub Division No.1 , Indore (MP)** on **03/11/2023** (date of inspection) in the presence of **Sr. Gerald, Holy Cross Convent , Indore**(name and addresses of the Manager/ Secretary or his representative) and that the building /premises is fit for occupancy upto classes Nur -XII (X/XII) with effect from 03/11/2023 for a period Of 1 years in accordance with rule.

Issued on 03/11/2023 at **Indore** by Sub Divisional Officer PWD Indore.


Sub Division Officer
PWD Distt. Sub Division No.1, Indore
Sub Divisional Officer
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE